

# Pairing Scanners for WMS

← IMPORTANT

## Step 1:

Using the USB Cable, plug the charging base into a computer. Set the scanner into the charging base. After a few seconds of beeping, the scanner will pair with the base. You may begin scanning the configuration barcodes.

## Step 2:

Scan Barcode "Charge only Mode"



## Step 3:

Scan Barcode "Bluetooth SSP On"



## Step 4:

Scan Barcode "Bluetooth HID Keyboard Connect"

After scanning, you will be able to pair the scanner with the tablet. It will first show up as 'Keyboard', but wait until the serial number appears before connecting.



## Step 5:

After the scanner is paired, scan Barcode "Auto Reconnect On"



BT\_ACM1.

**\* Auto Reconnect On**

## Step 6:

Scan QR Code in order to scan properly within WMS



PREBK29!

## Step 7:

Scan QR to put scanner in Silent Mode



**Silent Mode with Flashing LED -  
Cordless Scanner and Base**

## Troubleshooting

If there's any issue with scanning, you can always scan the default barcode. This will put it back to factory settings and you can start the process again.



DEFAULT.

# Formatting PalletID for Barcode Scanners

(scan left to right)



DFMBK3.


Enter Data Format



0  
x2




9  
x8



F  
x1




3  
x1



4  
x1



0  
x3



MNUSAV.

Save

Scan if you make a mistake going through the above:



MNUABT.

Discard